




1a
TOP VIEW



1b
SIDEVIEW




APPL #
10/796,538




APPL # 10/796, 538

36 FRONTVIEW 90°
TURN FROM FRONTVIEW

TREKING POLE RECEIVER LEGS
(POLE HANDLE RECEIVER)
(END LEGS)



POLE HANDLE




POLE HANDLE
RECEIVER HOLE

SIDE RAIL
RECEIVER
HOLE

3A SIDEVIEW

POLE HANDLE RECEIVER
CUP



SIDE RAIL
RECEIVER
HOLE


LOCK

LOCK
BOTTOM → SIDE RAIL


(3)

46
FRONTVIEW
90° TURN FROM
SIDEVIEW

ICE AX POINT RECEIVER LEGS



49 SIDEVIEW




4 of 5


APPL # 101796,538

56 FRONTVIEW
90° TURN FROM SIDEVIEW

ICE AX SHAFT RECEIVER LEG



5a SIDEVIEW



5 of 5
5